

Extension of the maintenance and repair instructions for SAF axles or axle suspensions with SKRB 9019K type 19.5" disc brakes, SKRB 9019W, SK 1000 ET 120

3) Replace with corrosion




Figure 1

Condition description:

Brake disc okay

Action:

Replacement not necessary!



Figure 2

Condition description:

Brake disc is not clearly in good condition

Action:

Replacement necessary within 6 months!



Figure 3

Condition description:

Brake disc not in good condition (2 - 4 layers of corrosion)

Action:

Immediate replacement necessary!